Mākaha Valley Flood Study

Community Meeting No. 2 September 23, 2014




 Report is available at: http://dlnreng.hawaii.gov/fcds/?p=493

Send comments by:

October 15th

Email:

bruce@townscapeinc.com gabrielle@townscapeinc.com













Agenda

- Project Background
- Existing conditions in Mākaha
- Recommended Flood Mitigation Measures
- Cost Estimates
- Prioritization of Projects
- Next steps

Project Background

- Funded by House Bill No. 2883 in 2012
- Appropriated \$500,000 for flood study

"The purpose of this Act is to require the Department of Land and Natural Resources to conduct a flood study for Mākaha Valley and investigate all potential funding sources to finance the flood study and any improvements or repairs as recommended by the flood study."


- Contracted Townscape, Inc. to conduct flood study
 - Subconsultants: Okahara and Associates







Project Scope and Schedule



Our Stakeholder Outreach Process

Community

- Community members
- Land owners
- Businesses


Public Agencies

- State Department of Transportation
- State Civil Defense
- City DPP Drainage, DPR, DFM
- Board of Water Supply


Elected Officials

- Representative Jo Jordan
- Senator Maile Shimabukuro

State Land Use Districts




Landowners




Large Undeveloped Parcels

- 13+ large undeveloped parcels
- Total 462 acres
- Zoning could allow for single family homes, hotels, duplex units, recreational facilities




Drainage Basins


- 75% of the valley drains into
 Mākaha
 Stream
- 25% of the valley drains into
 Eku Stream





Example of "Well-Planned" Drainage System





Mākaha Valley Current Drainage System: "Piece-meal"












Project No.01: Eku Stream Channel and Off-line Detention Basin




Eku Stream - Gabion Rock Channel

Looking Makai



Project No.01: Eku Stream Channel and Off-line Detention Basin




Eku Stream - Concrete Channel

Looking Makai


Project No. 02: New Eku Stream Bridge at Farrington Highway






Project No. 03: Repair the Breach in the Mākaha Stream berm






Repair Makaha Stream Berm

Looking Westerly




Project No. 04: Mākaha Stream Levee




Makaha Stream Levee

Looking Makai




Project No. 05: Kili Drive Channel




Kili Drive - Concrete Channel


Looking Makai




Project No. 06: Restore Mākaha Surfing Beach "Pond"










Stream Channel Maintenance



Storm Drain Maintenance



Forest Restoration



- Infiltration rates 2X greater
- 2/3 of valley is forested areas
- Long-range project
- ✓\$500,000 GIA
- ✓\$250,000 BWS
- ✓\$250,000-\$500,000 NRCS grant application

Other Non-Structural Measures

- Enforcement of existing legislation
 - ROH Chapter 41, Article 26: Maintenance of streams → Owner is responsible to maintain stream
 - ROH Chapter 29, Article 4: Litter Control→ Illegal to litter in any stream






Other Non-Structural Measures

Drainage Improvements required for future development

 Any future development of zoned/undeveloped parcels should include a combination of on-site storm runoff detention and improvement of downstream

drainage systems



Cost Estimates

	Mitigation Measure	Total Estimated Cost*
1	Eku Stream Channel and Off-line Detention Basin	\$27.8M-\$34.8M
2	Mākaha Stream Levee	\$17M-\$24M
3	New Eku Stream Bridge at Farrington Highway	\$12M-\$19M
4	Kili Drive Channel	\$12M-\$19M
5	Repair the breach in the Mākaha Stream berm	\$1.7M-\$3.3M
6	Noholio Road Drain Line	\$1.7M-\$3.3M
7	Restore Mākaha Surfing Beach "Pond"	To be determined
8	In-stream Detention Basins for Mākaha Stream	To be determined

^{*} Includes land acquisition, easements, environmental fees, survey and design, construction management, and construction costs

Prioritization of Projects

High	Medium	Low
 Repair the breach in the Mākaha Stream berm Restore Mākaha Surfing Beach "Pond" 	 Eku Stream Channel and Off- line Detention Basin 	 Kili Drive Channel Mākaha Stream Levee Noholio Road Drain Line In-stream Detention Basins for Mākaha Stream New Eku Stream Bridge at Farrington Highway

Implementation of the Mākaha Valley Flood Study

- Difficulties with implementation:
 - Privately-owned land
 - Significant capital funds needed
 - Ongoing maintenance of projects
- Challenges:
 - Identify funding sources for projects
 - Identify entity that will own and maintain improvements


Next Steps

December 2014:

FINAL Report

January 2015:

3rd Community Meeting



Thank you for your attention.

Questions?



Contact Information:



Bruce Tsuchida 808-536-6999 bruce@townscapeinc.com Gabrielle Sham 808-536-6999 gabrielle@townscapeinc.com